

APP GUIDE JULY 2007





www.LSD-DOORS.com

Application- / Price-list

(USA suggested retail price)

(Effective May 27,2007)

Manufacturer / Vehicle Type	Type	Model	Year of construction	Footnotes	Part No.	MSRP
ACURA						
Integra	DC2		94-01	a), b), d), f), j)	50050007	\$1.599,00
RSX	DC5	All	02+	a), b), c), f)	50050006	\$1.599,00
AUDI						
A3	8P	2-Door	03+	a), b), d), f), j), p)	50010003	\$1.999,00
A4	B5	4-door	95+	a), b), d), f), j), o)	50010006	\$2.099,00
TT	8N	incl. Roadster	98+	a), b), d), f), l), j)	50010002	\$2.099,00
BUICK						
Regal, Grand National	G-Body	manual windows	80-87	a)	50061008	\$1.999,00
	G-Body	electric windows	80-87	a), d)	50061010	\$1.999,00
BMW						
3 series (E36)	3C, 3/C, 3/CG	Compact	94-98	a), b), d), j)	50020002	\$1.799,00
	3C, 3/C, 3/CG	Coupe	94-98	a), b), d), j)	50020009	\$1.799,00
3 series (E46)	346C, 346R	Coupe, Convertible	99-05	a), b), d), j)	50020003	\$1.899,00
M3	M346	Coupe	00+	a), b), d), j)	50020003	\$1.899,00
	M346	Convertible	01+	a), b), d), j)	50020010	\$2.099,00
Z 3	R	Roadster	96-02	a), b), d), j), k)	50020005	\$2.199,00
Z 4	Z 85	Roadster	03+	a), d), f), j)	50020006	\$2.199,00
CADILLAC						
Escalade		including EXT,ESV	2002-06	a) d) j) k) l)	50063001	\$2.099,00
CHEVROLET/ GMC						
Caprice			92-96	a), d), l)	50061011	\$1.999,00
Cavalier	RS/Z24	Convertible	95-04	a), b), d), j)	50061001	\$1.599,00
	RS/Z24	Coupe	95-04	a), b), d), j)	50061002	\$1.599,00
	RS/Z24	4 door model	95-04	a), d), j)	50061003	\$1.599,00
Cobalt		All	05+	a), d), j)	50061016	\$1.599,00
Colorado, Canyon		All	05+	a), d), l)	50061006	\$1.999,00
Corvette	C-5	Coupe, Convertible	97-04	a), b), d), j)	50061009	\$2.299,00
	C-6	Coupe, Convertible	05-06	a), b), d), j)	50061012	\$2.299,00
C-1500 1/2 ton		Standard, ext. Cab	88-98	a) d) j) k) l) p)	50061007	\$1.999,00
El Camino, Malibu, Monte Carlo SS	G-Body	manual windows	80-87	a), i)	50061008	\$1.999,00
	G-Body	electric windows	80-87	a), d), i)	50061010	\$1.999,00
Impala	SS		92-96	a), d), l)	50061011	\$1.999,00
Impala			97-04	a) d) j) l)	50061014	\$1.999,00
Silverado, Sierra	New body style		2007+	a) d) j) k) l)	50061013	\$1.999,00
Silverado, Sierra		Standard, extended, crew	99-06	a) d) j) k) l)	50061005	\$1.999,00
Tahoe, Yukon, Suburban, Avalanche	New body style		2007+	a) d) j) k) l)	50061013	\$1.999,00
Tahoe, Yukon*, Suburban, Avalanche*	*will not work with factory equipped body cladding		00-06	a) d) j) k) l)	50061005	\$1.999,00
S-10/S-15 Standard and Ext-cab only		2-door Truck only	94+	a) d) j) k) l)	50061004	\$1.599,00
CHRYSLER						
300/300C		4 door model	05-06	a), d), j)	50027004	\$1.999,00
Crossfire	ZH	Coupe only	04+	a), b), c), i), j)	50027005	\$1.799,00
PT Cruiser	PT	4 door model only	01+	a), d), f), j)	50027003	\$1.599,00
DODGE						
Charger			05+	a), d), j)	50027004	\$1.999,00
Magnum	RT/SXT	All	05+	a), d), j)	50027004	\$1.999,00
Neon	PL	4 door model	95-99	a), d), j)	50027001	\$1.599,00
		2 door model	95-99	a), b), d), j)	50027006	\$1.599,00
		4 door model	00-05	a), d), j)	50027002	\$1.599,00
FERRARI						
Modena	F131	Coupe, Spider	00+	a), b), c), j)	50042001	\$4.899,00
FORD						
Focus	DAW,DBW,DFW, DNW, DA1, DB1	Lim., 2 door model	98-04	a), b), d), g), j)	50030001	\$1.599,00
		4 door model	98-04	a), d), g), j)	50030002	\$1.599,00
Expedition			97-02	a), d), l)	50030004	\$1.999,00
F-150 Standard Cab, Extended Cab		Standard, extended cab	04-07	a), d), l)	50030003	\$1.999,00
F-150 Crew Cab		4-door model only	04-07	a), d), l)	50030013	\$1.999,00
F-150 Standard Cab, Extended Cab			97-03	a), d), l)	50030006	\$1.999,00
F-150 Crew Cab		4-door model only	97-03	a), d), l)	50030004	\$1.999,00
F-250, F-350, F-450, F-550, F-650			1999-2007	a), d), l)	50030009	\$1.999,00
Mustang		Coupe	99-04	a), d)	50030008	\$1.999,00
Mustang		Coupe	05+	a), b), d), j)	50030005	\$1.999,00
HONDA						
Civic, CRX	EC8,9,ED6,7,9,EE	2 door	88-91	a), b), d), f), j)	50050003	\$1.599,00
		2 door,Del Sol	92-95	a), b), d), f), j)	50050003	\$1.599,00
		2 door Hatchback	96-00	a), b), d), f), j)	50050005	\$1.599,00
		2 door Coupe	92-95	a), b), d), f), j)	50050015	\$1.599,00
		2 door	2001-2005	a), b), c), f)	50050006	\$1.599,00
Civic	EP1,2,3,4,EM2,EV	2 door Coupe & Si	2006+	a), b), d)	50050011	\$1.599,00
Ridgeline			05+	a), d), j)	50050010	\$1.999,00
S 2000	AP 1		00+	a), d), j)	50050008	\$1.999,00

HUMMER						
H2			03-05	a), d), j), q)	50099001	\$2,499.00
Hyundai						
Tiburon	GK		03+	a), b), d), j)	50066001	\$1,799.00
LAMBORGHINI						
Gallardo			03+	a) b), d), j), k), p)	50011001	\$4,999.00
MAZDA						
Miata	NA		90-98	a), b), d), h), j)	50075001	\$1,699.00
	NB		99-05	a), b), d), h), j)	50075002	\$1,699.00
	NC		05+	a), b), d), j)	50075004	\$1,799.00
RX8	SE	Coupe	03+	a), d), j)	50075003	\$1,799.00
Manufacturer / Vehicle Type	Type	Model	Year of construction	Footnotes	Part No.	MSRP
MERCEDES						
CL	215	Coupe	99+	a), b), d), j)	50025006	\$3,499.00
CLK	208	incl. Convertible	97-02	a), b), d), j)	50025004	\$2,299.00
CLK	209	incl. Convertible	03+	a), b), c), j)	50025005	\$2,299.00
SL	230		01+	a), b), d), j)	50025003	\$2,999.00
SL	129		89-00	a), b), d), j)	50025007	\$2,999.00
SLK	170		96-04	a), d), i)	50025001	\$2,299.00
	171		04.-07	a), b), d), J)	50025002	\$2,299.00
MINI						
Mini	R50, Mini	incl. Convertible	02+	a),b) d), f), i) j), k)	50020007	\$1,899.00
MITSUBISHI						
Eclipse	D30	Coupe, Spyder	95-99	a), b), d), f), j)	50065002	\$1,799.00
NISSAN						
350Z	Z33	incl. Convertible	03+	a), d), j)	50085001	\$1,899.00
300Z			90-96	a), d), j)	50085003	\$1,899.00
OLDSMOBILE						
Cutlass, 442	G-Body	manual windows	80-87	a)	50061008	\$1,999.00
	G-Body	electric windows	80-87	a), d)	50061010	\$1,999.00
PONTIAC						
Sunfire		Convertible	95-04	a), b), d), j)	50061001	\$1,599.00
		2 door model	95-04	a), b), d), j)	50061002	\$1,599.00
		4 door model	95-04	a), d), j)	50061003	\$1,599.00
PORSCHE						
911	996	all types	99-04	a), b), c), i), j), o)	50071002	\$3,499.00
911	997	Carrera	04+	a), b), c), i), j), o)	50071001	\$3,499.00
Boxster	986	incl. Boxster S	98+	a), b), d), i), j), o)	50071003	\$2,999.00
Boxster	987	incl. Boxster S	04+	a), b), c), i), j), o)	50071004	\$2,999.00
Cayman	987	Coupe	06+	a), b), c), i), j), o)	50071004	\$2,999.00
TOYOTA						
Celica	T23	Coupe	00+	a), b), c), f), j)	50056001	\$1,799.00
MR2	W2, W20	Coupe	89-00	a), b), d), f), j)	50056004	\$1,799.00
	W3	Convertible	00+	a), b), c), f), j)	50056002	\$1,799.00
Scion TC			05+	a), d)	50056003	\$1,699.00
Scion XB			04+	a), d)	50056005	\$1,699.00
VOLKSWAGEN						
Corrado	53i		88-94	a), b), d), f), j)	50080022	\$1,699.00
Golf II	19E		85-92	a), b), d), f), j)	50080002	\$1,699.00
Golf III	1HXO,1H	2 door model	93-99.5	a), b), d), f), j)	50080003	\$1,699.00
	1HXO,1H	4 door model	93-99.5	a), d), f), j)	50080023	\$1,699.00
	1E	Convertible	93-99.5	a), b), d), f), j)	50080013	\$1,699.00
Golf IV	1J	2 door model	99.5-05	a), b), d), f), j)	50080004	\$1,699.00
		4 door model	99.5-05	a), d), f), j)	50080014	\$1,699.00
Golf V		2 door model	.06-07	a), b), d), j)	50080005	\$1,699.00
		4 door model	.06-07	a),d), j)	50080008	\$1,699.00
Jetta III	1HXO,1H	4 door model	93-99.5	a), d), f), j)	50080010	\$1,699.00
Jetta IV	1J	Sedan.; Station Wagon	99.5-04	a), d), f), j)	50080009	\$1,699.00
Passat	3B, 3BG	Wagon	96+	a), d), f), j)	50080015	\$1,699.00
DISPLAYS						
LSD Presentation Display		Stand with 1 hinge			46030001	\$650,00

Prices are subject to change without notice

Footnotes:

TBA = please call for anticipated delivery date

a) dismantling and slight modification of the fender might be necessary

b) only for 2-door models

c) the original wire harness can be used by rerouting, therefore a drill hole in the A-pillar might be necessary. For further information, please check the installation

d) the wire harness extension is necessary

f) the standard indicator at the fender has to be slightly modified or replaced.

g) the original windshield washer reservoir must be replaced by Ford part-no.: Nr.2S61.17618-AD and the cover 1142518

i) original windshield washer reservoir must be modified/made smaller or changed. Please check the chart with accessories for a replacement windshield washer

j) vehicles with airbags in the doors - the functionality of the airbag needs to be tested after the cable is extended

k) parts of the original hinges need to be cut off. To go back to the original hinges there will be additional parts necessary. Please check the chart with accessories

l) internal fender modification required

o) the cover of the charcoal filter needs to be modified

p) internal door modification required-welding and paint work necessary

q) 2004+ models must purchase antenna relocater kit 6852096

There will be no warranty for changes at the construction method of the car manufacturer or tolerances of a vehicle type!

Chart with accessories

Footnote	Addition for part #	Manufacturer / Vehicle Type	Accessorie Part	Part #	MSRP
i)	50010002	Audi TT	Windshield washer reservoir	68520001	\$149,00
i)	50020007	BMW Mini	Windshield washer reservoir	68520002	\$139,00
i)	50020007	BMW Mini with Xenonlight	Windshield washer reservoir	68520003	\$149,00
k)	50020007	BMW Mini	Door hinge set	50100017	\$299,00
i)	50025001-50027005	Mercedes SLK Type 170, Chrysler Crossfire	Windshield washer reservoir	68520009	\$149,00
i)	50071002 + 3	Porsche 986 / 996	Windshield washer reservoir	68520006	\$149,00
i)	50071002 + 3	Porsche 986 / 996 with Xenonlight	Windshield washer reservoir	68520007	\$160,00
i)	50071001 + 4	Porsche 987 / 997	Windshield washer reservoir	68520004	\$149,00
i)	50071001 + 4	Porsche 987 / 997 with Xenonlight	Windshield washer reservoir	68520005	\$189,00
q)	50099001	Hummer H2 04+	Remote mounted antenna	68520906	\$81,00
		Protective Corrosion Inhibitor Spray 80ml bottle		68520900	\$6,75

Contents of delivery:

All LSD solutions come completely pre-assembled right out of the box, including all necessary installation plug connectors and insulation materials for the extension of the -supplied by customer - original wire here

Delivery time:

In stock products ship within 3 - 5 days, subject to prior sale


Our delivery program is growing steadily! Check the new applications at www.lsd-doors.com

Important footnote for the gas springs:

- the gas spring was balanced due to the weight of a original door without any additional accessories. If there is a difference in the weight of the c need to purchase a stronger or weaker gas spring at additional cost.
- Please note, that the gas power of the gas springs may change due to temperature variations, this may alter the force required to open and clos These variations are normal and are due to the nature of gas springs and should not be considered a defect.

Gas Springs Chart:

MSRP					Uniball-bearing mountin	
	\$79,00	\$99,00	\$99,00	99,00	\$10,00	\$10,00
Force	no uniball-bearing mountings	Gas spring length A= 285mm/11,2Inches	Gas spring length A= 282mm/11,1Inches	Gas spring length A= 279 mm/11 Inches	uniball-bearing mounting short (44 mm/1,73 Inches)	uniball-bearing mounting long (47 mm/1,85 Inches)
1100 N	64900110	64901110	64902110	64903110,00	68310641	68310541
1900 N	64900190	64901190	64902190	64903190,00		
2100 N	64900210	64901210	64902210	64903210,00		
2300 N	64900230	64901230	64902230	64903230,00		
2450 N	64900245	64901245	64902245	64903245,00		
2600 N	64900260	64901260	64902260	64903260,00		
2750 N	64900275	64901275	64902275	64903275,00		
2900 N	64900290	64901290	64902290	64903290,00		
3100 N	64900310	64901310	64902310	64903310,00		
3300 N	64900330	64901330	64902330	64903330,00		



LSD Doors - North America
 A brand of KW automotive NA, Inc.
 1075 North Avenue Sanger, CA 93657
 Phone: 559.875.0222
 Fax: 559.876.2259
 info@lsd-doors.com www.lsd-doors.com